This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al. DOCKET: 135830 ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070



GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al. DOCKET: 135830

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070



GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al.

DOCKET: 135830 ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070





FIG. 3

GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al. DOCKET: 135830


ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070

4/6



GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al. DOCKET: 135830

ATTY: ROBERT B. REESER, III; PHONE: (314) 621-5070



GAS TURBINE HEAT EXCHANGER ASSEMBLY AND METHOD FOR FABRICATING SAME INVENTOR: PETER R. HULL, et al. DOCKET: 135830 ATTY: ROBERT B. REESER, III; PHONE: (314) 621–5070

